

EPT E CATALOG - PART DETAIL


Browning 3TB50

Cast Iron, 3 Groove, A or B Belt, Split Taper Sheave, Uses P1 Bushing



Images may not be an exact representation of the product

Product Type:	Split Taper Sheave
Type of Belt:	A, B
Number of Grooves:	3
Bore (Min):	0.5
Bore (Max):	1.75
Bushing Used:	P1



Part No	Description	PD (A)	DD (A)	PD (B)	DD (B)	OL
1001684	3TB50	4.8	4.6	5.3	5	2.703125
OD	F	L	P	C	X	G
5.35	2.5	1.9375	0	0.5625	1.3125	0.625
E	H					
0.203125	3					